Mobile digital amplifier for strain gauge

Safety warnings



General: When mounting, initiating and operating this measuring amplifier the safety precautions and regulations have to be observed. Only staff with a corresponding qualification should work with the measuring amplifier. A non-observance of the safety regulations may cause serious injuries and/or damages. Check before initial operation the suitability of the measuring amplifier for this area of application. The technical data of this manual have to be followed.

Characteristics



Input: 2 strain gauge full bridges (350 ohms) / Input sensitivity: 0,1...5 mV/V

Sensor supply: 5 VDC / Analogue output: 4...20 mA / 0...10 V

Digital output: 2 interface RS232 / Voltage supply: Internal accumulator

Option: external supply / Resolution: 12 / 14 / 15 / 16 bit

Combined error: 0,2% of end scale value / Indication:LCD-display

Memory: peak values / Degree of protection: IP 54 Adjustment: with RS232 interface and software with programming keys of display

Optinally: adaptor for connection of strain gauge sensor

Supplied with: counter plugs and protection kit

Connector plugs

Supplied connector plugs:

2x 7-pole (Binder 423 series) to connect strain gauge

1x 8-pole DIN 45326 (Binder 423 series) to connect analogue outputs

Pin assignment: view on soldered connection of pin insert




Connection strain gauge bridge Connection cable Ø4...7 mm Wires up to 0,75 mm²




Connection analogue outputs Connection cable Ø4...7 mm Wires up to 0,75 mm²

Connection top side



When using the battery charger (see accessoriers), it is possible to operate the measuring amplifier with discharged accumulator. The accumulator will be charged at the same time. An empty accumulator has a charging time of approx. 30 hours.

Connection strain gauge



Input strain gauge 2

S+ + S- L L


1 2 3 4 5 6 7

Connection 3/4 and 6/7: + and ▲ of bridge supply 5 VDC

Connection 2 and 5: output signal of bridge S+ and S-


Connection 1: Shield of connection cable (bridged internally with ▲)

Analog outputs



Connection 5: output voltage + strain gauge 1 (0...10 VDC)
Connection 4: output voltage + strain gauge 2 (0...10 VDC)
Connection 7: ouput current + strain gauge 1 (4...20 mA)
Connection 6: output current + strain gauge 2 (4...20 mA)

Connection bottom



Programming: When using the software for visualization it is possible to do the settings of each strain gauge amplifier via interface RS232.

Normal operation: It is possible to read out the current measured value of the strain gauge amplifier with a terminal program and then process it.

Setting into operation

Connect the strain gauge sensor(s) to the mobile amplifier, using the adaptor(s) or the 7-pole plug(s). Switch on the device. The backlighting of the display is switched on momrntary, the version of the LCD-software (**LCD v. 1.0x**) and of the software for the amplifier (**CPU v. 10x**) is indicated in succession. After that the device is turning to normal operation (Indication: **totAl 0**).

When switching on the device and no strain gauge sensor is connected, for approx. 30 seconds **HI----** is indicated for the the corresponding channel. This indication appers too, when the connected sensor is used above the adjusted upper limit value. When the sensor is used below the adjusted lower range limit, the dication is **LO----**. If the device is in operation and a strain gauge sensor is connected, the corresponding channel changes into normal operation automatically.

Ν	lote	25	a	C	Cι	ım	u	a	to	r

If the power unit is connected,	the accumulator is charged.	Indication:	and 💶	are switched on one	after
the other and switched off.					

If no power unit is connected, the current state of charging is indicated:

Full	accumu	lator
- гин	accumu	aw

Half-full accumulator

blinking, accumulator low (should be charged)

If the accumulator is discharged, **Batt Lo** / **shut off** is indicated (switch off the device to avoid a total discharge or operate the device with a connected battery charger.

The device has no automatic switching-off, when accumulator is discharged. To avoid a total discharge, switch off the device with the switch.

Notes program numbers

- PN 43: Tare key (value 0 = not active / value 1 = Tare when pressing a short time / value 2 = Tare when pressing more than 2 seconds)
- PN 188: Backlighting (value -1 = always on / value 0 = off / value 1...300 = operating time in seconds after pressing a key). The standard configuration is -1
- PN 189: Brightness of backlighting (value 0...100 (in %) The standard configuration is 3 (uisable for dark surroundings)
 - The brighter the backlighting the shorter life of the accumulator.

Notes interfaces

When activating the on-line operation with the software: indication **PCCon CH 1** for RS232 strain gauge 1, **PCCon CH 2** for RS232 strain gauge 2. The respective indication appears also for a short time, when the measuring amplifier is connected with an interface circuit to a PC.

MANUAL


Display

Line 1 (channel 1 for strain gauge 1)

Line 2 (channel 2 for strain gauge 2)

Line 3

Line 4



Indicates the measured value of strain gauge 1. Open input circuit: no indication

Indicates the measured value of strain gauge 2. Open input circuit: no indication

Indicates in normal operation totAl

Indicates the sum of line 1 and line 2

Note: Line 1 and line 2 are indicating "HI" for a while, when switching on power and no strain gauge is connected

1411141

Programming

Besides programming the ADLM-HD via serial interface it is possible with the keys of the display, too. In this case some program numbers cannot be used.

Control keys



Function of keys

increase address or value

P ESC (leave editing mode / programming mode or reject input)

decrease address or value

T enter (accept address or value)

1.0 Programming mode (programming mode not interlocked)

To enter programming mode, press keys ▲ and ▼ simultaneously. Indication: **SELECt L.1**Select the programming level by pressing ▲ or ▼ and confirm 2 times with **T**. Indication: **Prog** and **SELECt CH.1**.
Continue with 2.0

1.1 Programming mode (programming mode interlocked)

To enter programming mode, press keys A and Simultaneously. Indication: SELECt L.1

Select the programming level by pressing or Input the pin code (four-digit, standard is 5032) with or Indication: Prog and SELECt CH.1. Continue with 2.0

simultaneously. Indication: SELECt L.1

and confirm with T. Indication: CodE:L.x (x = programming level)

or Indication: Prog and SELECt CH.1. Continue with 2.0

Selecting channel

Select channel with or and confirm with **T**. Indication: **CH1** (small), in line 1 the first available address and in line 2 the value stored under this address (eg in program level 1 and channel 1: line 1: **0** / line 2: **1.03** (version of software))

Selecting address

Select address with ♠ or ▼. Indication line 1: address / Indication line 2: stored value under this address. Confirm the selected address with T. Indication: ↑ (editing mode, small characters) / line 1: stored value under this address / line 2: changeable value in editing mode, can be stored under the selected address.

Editing mode

The editing mode is indicated with $\P \$. The top line of the display indicates the value which is stored with the selected address. This indication is for support. The value of the lower line can be changed when pressing the \triangle or \bigvee key. With key T this value is stored. The display indicates the proper transfer of data with \bigvee . If the transfer of data was faulty this is indicated with \bigvee . Pressing the T key the editing mode is left and by pressing the \triangle or \bigvee key another address can be selected.

The editing mode can be left when pressing the **P** key, too. In this case all changings with this address will not be stored and a new address can be selected by pressing the **A** or **V** key.

When pressing the \triangle or ∇ key (in editing mode) a longer time the unit position changes first (20 counts), then the tens digit, the hundreds digit and in the end thousands digit (each 20 counts).

Leaving programming mode

To leave the programming mode, the ${\bf P}$ key has to be pressed.

Programming software

Notes

Before completing the link (online-mode) via the RS232-interface to the measuring amplifier, the display module has to be switched over in programming mode by pressing the **a** and **v** key. The display indicates this mode with **Prog**.

If any key of the display module is pressed during online mode, the display is reset every 4 seconds (all symbols flash). The ADLM-HA is in normal mode, as soon as the PC-software has sent the command for offline mode.

If the PC software is switched over into offline mode and no key of the display module was pressed during online mode, the programming mode has to be left by pressing the **P** key. Then the ADLM-HA is in normal mode.

If the PC software is quitted without switching over into offline mode, the voltage supply of the ADLM-HD has to be disconnected temporarily.

	addr.	status	function	bytes	value	WE	F1	E2	F3
MANUAL	0 1 2 3 4 5 6 7 8	R R/W R/W R/W R/W R/W R/W R/W W	version software (xx.yy / x=MSB, y=LSB) strain gauge voltage (mV) sensitivity (µV/V) amplification resolution measuring cycle (ms) minimum AD-value maximum AD-value tare offset tare trigger	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1/2/4/8 12/14/15/16 bit	0	x x x x x x	x x x x x x x x	x x x x x x x x x
	10 11 12 13 14	R/W R/W R/W R/W	0% calibration current output 100% calibration current output measuring period (ms) behaviour on error value for error	2 2 2 2 2			X X X	X X X X	X X X X
	20 21 22 23 24	R/W R/W R/W R/W	0% calibration voltage output 100% calibration voltage output measuring period (ms) behaviour on error value for error	2 2 2 2 2			X X X	X X X X	x x x x x
	30 31 32 33 34 35 36 37 38 39	R/W R/W R/W R/W R/W R/W R/W R/W R/W	baud rate start bits data bits parity stop bits protocol 0% value indication 100% value indication test load decimal-place	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		1	x x x	x x x x x x x x x	x x x x x x x x x
	40 41 42 43 44	R/W R/W R/W R/W	company logo unit line 1 unit line 2 tare key mode sum up		0/1/2/3/4/5/6/7/8 0/122 0/135 0/1/2 0/1/3		X X X X	X X X X	X X X X
MANUAL	50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66	R/W R/W R/W R/W R/W R/W R/W R/W R/W R/W	IST 0 IST 1 IST 2 IST 3 IST 4 IST 5 IST 6 IST 7 IST 8 IST 9 IST 10 IST 11 IST 12 IST 13 IST 14 IST 15 IST 14 IST 15 IST 16	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2				x x x x x x x x x x x x x x x x x x x	x x x x x x x x x x x x x x x x x x x
	70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86	R/W R/W R/W R/W R/W R/W R/W R/W R/W R/W	SOLL 0 SOLL 1 SOLL 2 SOLL 3 SOLL 4 SOLL 5 SOLL 6 SOLL 7 SOLL 8 SOLL 9 SOLL 10 SOLL 11 SOLL 12 SOLL 13 SOLL 14 SOLL 15 SOLL 15 SOLL 16	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2				x x x x x x x x x x x x x x x x x x x	x x x x x x x x x x x x x x x x x x x
MANUAL	90 100 101 102 103 104 105 106 107	R/W R/W R/W R/W R/W R/W R/W R/W	customized serial number AD-Value: G= 1 / Res= 12 / Inp= -20 mV AD-Value: G= 1 / Res= 12 / Inp= +20 mV AD-Value: G= 1 / Res= 14 / Inp= -20 mV AD-Value: G= 1 / Res= 14 / Inp= +20 mV AD-Value: G= 1 / Res= 15 / Inp= -20 mV AD-Value: G= 1 / Res= 15 / Inp= +20 mV AD-Value: G= 1 / Res= 16 / Inp= -20 mV AD-Value: G= 1 / Res= 16 / Inp= +20 mV AD-Value: G= 1 / Res= 16 / Inp= +20 mV	16 2 2 2 2 2 2 2 2 2				х	x x x x x x x x

TRANSMITTER/TRANSDUCER - 6 - TRANSMITTER/TRANSDUCER

Addresses continued

Addre	esses	continuea						
addr.	status	function	bytes	valueert	WE	E1	E2	E 3
110	R/W	AD-value: G= 2 / res= 12 / inp= -10 mV	2					
111	R/W	AD-value: G= 2 / res= 12 / inp= +10 mV	2					X X
112	R/W	AD-value: G= 2 / res= 14 / inp= -10 mV	2					X
113	R/W	AD-value: G= 2 / res= 14 / inp= +10 mV	2					X
114	R/W	AD-value: G= 2 / res= 15 / inp= -10 mV	2					Х
115	R/W	AD-value: G= 2 / res= 15 / inp= +10 mV	2					Х
116	R/W	AD-value: G= 2 / res= 16 / inp= -10 mV	2					Χ
117	R/W	AD-value: G= 2 / res= 16 / inp= +10 mV	2					Χ
120	R/W	AD-value: G= 4 / res= 12 / inp= -5 mV	2					Х
121	R/W	AD-value: G= 4 / res= 12 / inp= +5 mV	2					Χ
122	R/W	AD-value: G= 4 / res= 14 / inp= -5 mV	2					Χ
123	R/W	AD-value: G= 4 / res= 14 / inp= +5 mV	2					Χ
124	R/W	AD-value: G= 4 / res= 15 / inp= -5 mV	2 2					Χ
125 126	R/W R/W	AD-value: G= 4 / res= 15 / inp= +5 mV	2					X
127	R/W	AD-value: G= 4 / res= 16 / inp= -5 mV AD-value: G= 4 / res= 16 / inp= +5 mV	2					X X
		•						
130 131	R/W R/W	AD-value: G= 8 / res= 12 / inp= -2,5 mV	2 2					X
132	R/W	AD-value: G= 8 / res= 12 / inp= +2,5 mV AD-value: G= 8 / res= 14 / inp= -2,5 mV	2					X X
133	R/W	AD-value: G= 8 / res= 14 / inp= +2,5 mV	2					X
134	R/W	AD-value: G= 8 / res= 15 / inp= -2,5 mV	2					X
135	R/W	AD-value: G= 8 / res= 15 / inp= +2,5 mV	2					Х
136	R/W	AD-value: G= 8 / res= 16 / inp= -2,5 mV	2					Х
137	R/W	AD-value: G= 8 / res= 16 / inp= +2,5 mV	2					Χ
140	R/W	DA-value 4 mA	2					Х
141	R/W	DA-value 12 mA	2					Х
142	R/W	DA-value 20 mA	2					Χ
143	R/W	DA-value 0 V	2					Χ
144	R/W	DA-value 5 V	2					Χ
145	R/W	DA-value 10 V	2					Χ
150	R/W	GW1 switch off value	2		20	Х	Х	Χ
151	R/W	GW1 switch on value	2		10	Х	Х	Χ
152	R/W	GW1 switch off delay (ms)	2		0	Х	Х	Х
153	R/W	GW1 switch on delay (ms)	2		0	Х	Х	Х
160	R/W	GW2 switch off value	2		30	Х	Х	Χ
161	R/W	GW2 switch on value	2		40	Х	Х	X
162 163	R/W R/W	GW2 switch off delay (ms)	2 2		0 0	X	X	X
		GW2 switch on delay (ms)			U	Х	Х	Х
180	R/W R/W	memory value minimum	2 2				X	X
181 182	R/W	memory value maximum working hour meter s	2				X X	X X
183	R/W	working hour meter h	2				X	X
188	R/W	working time backlighting	-	-1 / 0 / 1300 (s)	-1	х	X	X
189	R/W	brightness backlighting		0100 (%)	3	Х	Х	Х
400		3 3 3	40	()				
190	R/W	serial number Müller	16				Х	X
191 192	R/W W	date (week= LSB / year= MSB) pin code level 1	2		5032	х	Х	Х
193	W	pin code level 2			5032	X	х	
194	W	pin code level 3			5032	X	X	х
195	W	pin code level 4		(factory-set only)	5032	Х	Х	Х
196	R/W	pin code preset		` , , , , , , , , , , , , , , , , , , ,	5032			Х
	_		_					
200	R	current measuring value	2			Х	Х	Х
201	R R/W	current AD-value	2			Х	Х	X
203		AD-value accumulator voltage				Х	Х	Х
210	W	test current output	2				Х	Х
211	W	test voltage output	2				Х	Х
240	R/W	dummy-int 0	2					Х
241	R/W	dummy-int 1	2					X
242 243	R/W R/W	dummy-int 2 dummy-int 3	2 2					X
243	R/W	dummy-int 3	2					X X
245	R/W	dummy-int 5	2					X
246	R/W	dummy-int 6	2					X
247	R/W	dummy-int 7	2					X
248	R/W	dummy-string 0	16					Х
249	R/W	dummy-string 1	16					Х
250	R/W	check sum addresses 1 - 199	2					Х
254	R/W	mode	2	0=normal 1=linearisation			Х	Х
255	R	version software (xx.yy / x=MSB, y=LSB)				Х	Х	Х

ADLM-HA

Power supply

Voltage: accumulator pack 6 round cells R6 (NiMH)

Capacity: 7,2 V 2 Ah

Power consumption: with options approx. 1 W

Battery charger: input: 230 VAC output: 9 V / 1 A

Ambient conditions

Operating temperature:-10...+60°C Storing temperature: -20...+70°C

Mechanics

Enclosure: mobilCase 181 x 138 x 32/38 mm extruded aluminium profile Material:

Colour: silver anodised

Degree of protection: IP 54

Weight: approx.900 g (with accumulator) Connection:

2x strain gauge: Binder 723 series, 7-pole panel jack, 09 0128 99 07)

analog output: 1x Binder 723 series, 8-pole

panel jack (09 174 90 08)

RS232 output: 2x SUB-D jack 9-pole charging jack: jack socket 3,5 mm

Accessories

Protection kit: 2 TPE covering caps with adjustable and

sturdy shoulder strap (supplied with device)

Counter plugs: 2 Binder 723 series 7-pole

1 Binder 723 series 8-pole (supplied with device)

Battery charger for internal accumulator Adaptor for connection of load cells V24 programming cable with software

<u>Input</u>

Sensitivity: 0,1...5 mV/V (programmable) Interface:

RS232 (for programming)

Output

each amplifier 2 outputs (programmable) Analogue: 0...10 V and 4...20 mA (standard)

Amplifier 1 / 2: 1 strain gauge full bridge (350 ohms)

optionally 2...10 V or 0...20 mA working resistance <500 Ohm Current:

load resistor > 600 Ohm Voltage: Interface: 1x RS232 (each amplifier) data format: ASCII (can be read out with any

terminal program) 5 VDC 30 mA maximum (each amplifier) Sensor supply:

Indication

Display: microprocessor based multifuntion indicator

with bachlighting (to switch on)

Function: 4 keys for programming

Indication: current values / minimum/maximum values

/ diagnostic values

Adjustment

RS232 with programming software Interface:

Keys: 4 keys of display module key on display PCB Tare: Measuring rate: 10 ms....5 s (programmable) Filter: 10 ms...5 s (programmable)

Accuracy

Resolution: 12 /14 /15 /16 bit

at measuring rate: 128 / 32 / 16 / 8 per second Combined error: +/- 0,2% of end scale value

Temperature coeff.: <50 ppm/K